



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION
INCLUSIVE OF PHOTOGRAPHIC EVIDENCE

Next





HENLEYS SECURITY DOORS

INTRODUCTION

The Test has been carried out for certification purposes using the most productive attack methods in a strictly controlled environment. The Testing Examiner uses a defined set of tools allocated for use in each resistance class for a specified amount of time.

The testing house uses a steel framed construction with movable steel supports into which our test door is mounted.

Resistance (working) time

This is the Test time taken by the test examiner who carries out the burglar resistance test, in which specific tools are used to manipulate and attack the specimen.

Previous Next Home



Press Esc At Anytime To End The Presentation

BURGLARY RESISTANCE TESTING FOR LEVEL 1

A Series of 1 Minute Sustained Attacks



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

BURGLARY RESISTANCE TESTING LEVEL 1

DESCRIPTION OF ALL TOOLS PROVIDED TO THE EXAMINER

Various Sizes of Screwdrivers,
Crowbar, Wedges, Mole Grips, Pliers,
Spanners, Knife, Punches and
Examiners Physical Strength Including
Forceful Kicks and Blows



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar Knife and Forceful Kicks

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Middle Of The Door with Extreme Forward and Backward Kicks. Attack To The Lower Right Of The Door With The Use of A Crowbar. Attack To The Middle of The Door With The Use of A Sharp Knife (As Shown).

DURATION OF SPECIFIC ATTACK

1 Minute

OUTCOME

Minor Damage To External Face and Slam Strip.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lower Left of The Door With The
Use of A Crowbar (As Shown)

DURATION OF SPECIFIC ATTACK

1 Minute

OUTCOME

Minor Damage To External Face.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar and Screwdriver

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lower Left Of The Door With The Use Of A Crowbar. Attack To The Escutcheon With the Use Of A Crowbar and Screwdriver (As Shown)

DURATION OF SPECIFIC ATTACK

1 Minute

OUTCOME

Minor Damage To External Face. Escutcheon Removed.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lock Region Of The Door With The
Use of A Crowbar.

DURATION OF SPECIFIC ATTACK

1 Minute

OUTCOME

Minor Damage To External Face.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lock Region Of The Door With The
Use of A Crowbar and Screwdriver

DURATION OF SPECIFIC ATTACK


1 Minute

OUTCOME

Minor Damage To External Face.
NO ACCESS GAINED. PASS

CLOSE UP OF PREVIOUS SLIDE

[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 1

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lower Left Of The Door With The
Use of A Crowbar

DURATION OF SPECIFIC ATTACK

1 Minute

OUTCOME

Minor Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



END OF LEVEL 1 TEST

BURGLARY RESISTANCE TESTING FOR
LEVEL 1
SUCCESSFULLY PASSED



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

BURGLARY RESISTANCE TESTING FOR LEVEL 2

A Series of 3 Minute Sustained Attacks



[Previous](#) [Next](#) [Home](#)




HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

BURGLARY RESISTANCE TESTING LEVEL 2

DESCRIPTION OF ALL TOOLS PROVIDED TO THE EXAMINER

Various Sizes of Spanners, Lock Picking Tool, Various Sizes of Screwdrivers, Thin Nose Pliers, Knife, Pliers, Wedges, Crowbar, Mole Grips, Hammer, 18v-Battery Powered Drill, Drill Bits, Chisel, Manual Drill, Bolt Cutters, Metal Snips and Examiners Physical Strength Including Forceful Kicks and Blows



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Drill

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Middle of The Door With The Use
Of a Drill.

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Drill, Hammer, Screwdriver and Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Middle of The Door With The Use
Of a Drill, A Hammer, Screwdriver and A
Crowbar

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar, Hammer and Chisel

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Middle of The Door With The Use Of A Hammer and Chisel to Further Penetrate The Previously Made Hole. Attack To The Middle of The Door With A Hammer Landing Heavy Blows. A Fresh Examiner Takes Over and The Above Attack Process is Repeated.

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Manual Drill, 18V- Battery Powered Drill,
Crowbar, Hammer

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Door With The Use Of A Manual Drill. Attack To The Lower Middle of The Door With The Use Of An 18v- Battery Powered Drill, Crowbar and Hammer. Attack To The Lock Region With The Use of A Crowbar and Hammer. Attack To The Middle Left Around The Lock Area With The Use of A Crowbar. Attack To The Lower Left Slam Strip With The Use of A Crowbar. Attack To The Lower Right Hinge With The Use of A Crowbar.

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Minor Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar, Hammer, Wedges and Screwdriver

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lower Right Hinge With The Use of
A Crowbar, Wedges and Screwdriver.

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar, Hammer, Wedges, Chisel and Examiners
Forward Kicks

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lock Region With The Use Of A
Hammer, Wedges (As Shown) and A Series of
Forceful Front Kicks For A Sustained Amount of
Time. The Above Attack Process is Repeated
Several Times

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar, Hammer and Wedges

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS

CLOSE UP IMAGE
OF ATTACK TO LOCK REGION



Previous Next Home



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE
DISPLAYED)

Crowbar, Hammer and Wedges

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS

CLOSE UP IMAGE
OF ATTACK TO LOCK REGION



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Hammer, Crowbar and Mole Grips

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Lock Region and Door Handle With
The Use of A Hammer, Crowbar and Mole Grips.
Forceful Downward Blows With The Hammer.
Pulling and Prising action With The Crowbar.
Pulling and Bending Action With The Mole Grips.

DURATION OF SPECIFIC ATTACK

3 Minutes

OUTCOME

Door Handle Removed. Damage To External Face
and Damage to Outer Lock Plate.
NO ACCESS GAINED. PASS



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

Image Showing No Damage To
The Inside Face of The Door
Having Been Attacked From
The Outer Face, Displayed On
Previous Slide



Previous Next Home



BURGLARY RESISTANCE TESTING LEVEL 2

Image Showing No Damage
To The Inside Face of The
Door, Door Handle and Door
Lock Having Been Attacked
From The Outer Face



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 2

At This Stage, The Door Has Withstood A Series of Specifically Targeted Attacks For A Period of time Totalling 28 Minutes and Still Remains Un-penetrated

Image Showing The Door Having Minimal Resulting Damage



[Previous](#) [Next](#) [Home](#)



END OF LEVEL 2 TEST

BURGLARY RESISTANCE TESTING FOR
LEVEL 2
SUCCESSFULLY PASSED



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

BURGLARY RESISTANCE TESTING FOR LEVEL 3

A Series of 5 Minute Sustained Attacks



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

BURGLARY RESISTANCE TESTING LEVEL 3

DESCRIPTION OF ALL TOOLS PROVIDED TO THE EXAMINER

Various Sizes of Spanners, Lock Picking Tool, Various Sizes of Screwdrivers, Thin Nose Pliers, Knife, Pliers, Wedges, Mole Grips, Large Hammer, 18v-Battery Powered Drill and Drill Bits, Cold Chisel, Bolt Cutters, Axe, Large Crowbar and Examiners Physical Strength Including Forceful Kicks and Blows



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Axe, Large Hammer, Screwdriver, Crowbar and
Examiners Forceful Front Kicks, 18v-Battery
Powered Drill

DESCRIPTION OF SPECIFIC ATTACK

Attack To The Middle of The Door With The Use
of An 18v-Battery Powered Drill, Crowbar,
Screwdriver, Heavy Strikes From An Axe and
Heavy Downward Blows With A Large Hammer.
Attack To The Left Side of The Door Middle and
Left Side of The Door Lower Hinge With The Use
of A Crowbar

DURATION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Axe, Hammer, 18v-Battery Powered Drill ,
Screwdriver and Crowbar

DESCRIPTION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face.
NO ACCESS GAINED. PASS

VIEW OF ATTACK TO THE MIDDLE OF THE DOOR CLOSE UP



[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar

DESCRIPTION OF SPECIFIC ATTACK

Forceful and Determined Attacks To The
Lower Hinge and Surrounding Area With
The Use of A Crowbar

DURATION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS

CLOSE UP IMAGE OF ATTACK TO HINGE AND SURROUNDING AREA

[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar

DURATION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face and Door Frame.
NO ACCESS GAINED. PASS

CLOSE UP IMAGE
OF ATTACK TO THE MIDDLE
OF FRAME EXPOSING THE
STEEL FRAME

[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Large Hammer, Crowbar and Screwdriver

DESCRIPTION OF SPECIFIC ATTACK

Heavy Blows To The Lock Area of The Door With The Use of The Large Hammer. Pulling and Prising Action With The Crowbar and Picking of The Lock With The Screwdriver.

DURATION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face and Door Frame.
Minor Damage To Outer Lock Plate
NO ACCESS GAINED. PASS



Henleys Security Doors

[Previous](#) [Next](#) [Home](#)



BURGLARY RESISTANCE TESTING LEVEL 3

TOOLS USED IN SPECIFIC ATTACK (IMAGE DISPLAYED)

Crowbar, Hammer and Screwdriver

DURATION OF SPECIFIC ATTACK

5 Minutes

OUTCOME

Damage To External Face and Door Frame.
Damage To Outer Lock Plate.
NO ACCESS GAINED. PASS

CLOSE UP IMAGE OF ATTACK TO LOCK REGION



[Previous](#) [Next](#) [Home](#)



END OF LEVEL 3 TEST

TIME REMAINING TO ACHIEVE BR3
ACREDITATION

2 MINUTES

At This Stage, The Door Has Withstood A Series of
Specifically Targeted Attacks For A Period of time
Totalling 56 Minutes.



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

END OF TEST



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

Henleys have achieved over and above
the required standards to obtain the
prestigious Secured By Design status
which is awarded by the
Association of Chief of Police Officers



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

CONCLUSION

CERTIFICATION FOR BURGLARY RESISTANCE 2 STS202 SUCCESSFULLY AWARDED



[Previous](#) [Next](#) [Home](#)



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202
TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE



HENLEYS SECURITY DOORS

EXOVA WARRINGTON BURGLARY RESISTANCE STS202 TESTING DESCRIPTION INCLUDING PHOTOGRAPHIC EVIDENCE

Previous Home



Website: <http://henleyssecuritydoors.co.uk>

Birmingham & Midlands: 0121 308 5000
London & South: 0208 308 9500
Manchester & North: 0161 434 6000

Henleys Security Doors Ltd
Morford Road
Aldridge, Walsall
West Midlands, WS9 8TF

Email: info@henleyssecuritydoors.co.uk